



**PHOTO
INTERPRETATION
NOTE**

NATIONAL PHOTOGRAPHIC
INTERPRETATION CENTER

**IMPROVEMENT OF JAIME GONZALES AIRFIELD
CIENFUEGOS, CUBA**

DECLASS REVIEW BY NIMA / DoD

SECRET

R-17/72
MAY 1972
COPY NO 68
2 PAGES


W A R N I N G

This document contains information affecting the national defense of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

IMPROVEMENT OF JAIME GONZALES AIRFIELD,
CIENFUEGOS, CUBA

- 25X1A 1. Improvement of Jaime Gonzales Airfield [redacted] 25X1A
[redacted] has been observed on recent Old Head photography.
- 25X1A 2. The airfield is located just east-northeast of Cienfuegos, in south-central Cuba approximately 33.0 nautical miles (nm) southwest of Santa Clara Airfield [redacted] 25X1A
- 25X1D 3. An extension to the southern end of the NNE/WSW [redacted] main runway has been cleared and
25X1D graded since [redacted]. The runway [redacted]
extension was possibly serviceable on [redacted] and
25X1D measured at least [redacted] in length
(Figure 1). The combined length of the runway and extension
25X1D is at least [redacted] and is [redacted]
25X1D wide.
- 25X1D 4. Another improvement accomplished since [redacted] 25X1D
included surfacing of a [redacted] square parking
apron adjacent to the eastern edge of the main runway.
- 25X1D 5. Vegetation has been cleared since [redacted] from the
western segment of a former WNW/ENE runway, which had deteriorated.
- 25X1A 6. FRESCO (MIG-17) aircraft were observed for the first
25X1D time at this airfield on [redacted] photography of [redacted]
25X1A [redacted] when seven were present. None have been observed
there on [redacted] photography since that date.

NPIC/IEG/SGD/AB Project 150709NB



25X1D

FIGURE 1. IMPROVEMENT OF JAIME GONZALES AIRFIELD, CIENFUEGOS, CUBA

Approved For Release 2002/06/11 :
SECRET

Approved For Release 2002/06/11 :
SECRET